StarTech**.**com

Hard-to-find **made easy** ®

10-Port Industrial USB 3.0 Hub - ESD and Surge Protection

ST1030USBM

DE: Bedienungsanleitung - de.startech.com
FR: Guide de l'utilisateur - fr.startech.com
ES: Guía del usuario - es.startech.com
IT: Guida per l'uso - it.startech.com
NL: Gebruiksaanwijzing - nl.startech.com
PT: Guia do usuário - pt.startech.com

Packaging contents

• 1 x 10-port industrial USB 3.0 hub
• 1 x USB 3.0 host cable
• 1 x DIN rail mounting kit
• 1 x terminal block (2-wire)
• 1 x instruction manual

System requirements

• USB-enabled host computer with an available USB 3.0 port
• 2-wire 7~24V DC power source
• OS independent

Note: This hub can only be used with terminal block power input. A standard AC power adapter is not included or supported.

Operating system requirements are subject to change. For the latest requirements, please visit www.startech.com/ST1030USBM.

Product diagram

Front view

2-wire terminal block included
(7~24V DC input)
Power LED
USB 3.0 host port

USB 3.0 hub ports

*actual product may vary from photos

About USB 3.0 and USB 3.1 Gen1

USB 3.0 is also known as USB 3.1 Gen 1. This connectivity standard offers speeds up to 5 Gbps.

Installation

You must use the terminal block with your external power source to ensure sufficient power is delivered to each USB 3.0 port.

Connect the hub to a terminal block power source

1. If the terminal block connector is already inserted into the hub, remove it from the hub.
2. Loosen the two screws on the terminal block connector using a small Phillips or flat-head screwdriver.
3. Connect the power and ground wires from your DC power source to the proper terminal block connectors and fasten the screws. The terminals are marked on the hub's casing.

Note: Ensure that the polarity of the input power is correctly matched with the terminal block pins to ensure proper function (see the diagram below).

**+7~24V
GND**

4. Reinsert the terminal block into the hub. The Power LED on the hub should light up green.

Connect the hub to your host computer and peripherals

1. Connect the hub to an available USB port on your computer using the provided USB 3.0 A - B cable. Your computer's operating system should detect and automatically install the hub.
2. Connect your USB peripherals to the USB 3.0 hub ports.

Note: If the hub is connected to a USB 2.0 host port, it will operate at USB 2.0 speeds.

For the latest information, technical specifications, and support for this product, please visit www.startech.com/ST1030USBM.

Manual Revision: 07/23/2015

Mount the hub on a DIN rail or a surface

You can mount the hub on a DIN rail or a surface, such as a wall.

DIN rail mounting

1. Fasten and secure the provided DIN rail clips and screws to the rear of the hub.
2. Mount the hub on a DIN rail.

Surface or wall mounting

- Use the hub's integrated mounting holes and the screws provided to fasten and secure the hub to your wall or surface.

DIN rail clips

Wall mounting holes